


COURROIES CRANTEES - XH-



	Pas (pouce)	Pas (mm)	h ₁ (mm)	h ₂ (mm)
XH	7/8*	22,225	6,22	11,4

XH200 Largeur 50,80 mm		XH300 Largeur 76,20 mm		XH400 Largeur 101,60 mm		XH500 Largeur 127 mm	
Référence		Référence		Référence		Référence	
507XH200		507XH300		507XH400		507XH500	
560XH200		560XH300		560XH400		560XH500	
630XH200		630XH300		630XH400		630XH500	
700XH200		700XH300		700XH400		700XH500	
770XH200		770XH300		770XH400		770XH500	
840XH200		840XH300		840XH400		840XH500	
980XH200		980XH300		980XH400		980XH500	
1120XH200		1120XH300		1120XH400		1120XH500	
1260XH200		1260XH300		1260XH400		1260XH500	
1400XH200		1400XH300		1400XH400		1400XH500	
1540XH200		1540XH300		1540XH400		1540XH500	
1680XH200		1680XH300		1680XH400		1680XH500	
1750XH200		1750XH300		1750XH400		1750XH500	
				Longueur primitive		Nombre de dents	
				ISO (pouce)	ISO (mm)		
				50,7	1289,00	58	
				56,0	1422,00	64	
				63,0	1600,20	72	
				70,0	1778,00	80	
				77,0	1955,85	88	
				84,0	2133,60	96	
				98,0	2489,20	112	
				112,0	2844,40	128	
				126,0	3200,40	144	
				140,0	3556,00	160	
				154,0	3911,60	176	
				168,0	4267,20	192	
				175,0	4445,00	200	