



**Ref.
3191**

DIN
1814

Gira-Machos
Tap Wrench
Porte-Tarauds

Nº	Gama Uso Use Range	Gama Cuadradillo Square Range	Nº Art.	€
000	M 1 - M 8	2,10 - 4,90	69826	
010	M 1 - M 10	2,10 - 5,50	69828	
015	M 1 - M 12	2,10 - 7,00	69829	
020	M 4 - M 12	3,40 - 7,00	69831	
030	M 5 - M 20	4,90 - 12,00	69832	
040	M 11 - M 27	6,20 - 16,00	69834	
050	M 13 - M 32	7,00 - 20,00	69835	
060	M 25 - M 52	7,00 - 20,00	26694	

Nº 060 Acero / Steel / Acier



**Ref.
3192**

"T" +
Criqué

Gira-Machos
Tap Wrench
Porte-Tarauds

Nº	Mangos Shanks	Capacidad Capacity	L mm	Nº Art.	€
1	M 3 - 10	2,40 - 5,50	85	69837	
2	M 5 - 12	4,50 - 8,00	100	69838	
10	M 3 - 10	2,40 - 5,50	250	69840	
20	M 5 - 12	4,50 - 8,00	300	69841	



**Ref.
3409**

Extractor Tornillos
Screw Extractor
Extracteur Vis

INSTRUCCIONES USO:
1- Taladrar un Agujero Central con la Broca apropiada
2- Girar el Extractor hacia la izquierda hasta extraer el Tornillo

DIRECTIONS FOR USE:
1- Drill a Central Hole using a proper Drill
2- Turn Left the Extractor until the Screw is out

Nº	Para Tornillos de For Screws of		Nº Art.	€
010	M 3 - 6	1/8 - 1/4	2,70	40639
020	M 6 - 8	1/4 - 5/16	3,80	40641
030	M 8 - 11	5/16 - 7/16	4,90	40642
040	M 11 - 14	7/16 - 9/16	7,00	40644
050	M 15 - 18	9/16 - 3/4	9,00	40645
060	M 18 - 24	3/4 - 1"	12,00	40647
00001	Juego de Extractores del 1 al 6 Extractors Set from 1 to 6			75905

